

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1x.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-011839**Date Inspected:** 02-Feb-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 2300**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 730**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Jobsite**CWI Name:** N/A**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG segments**Summary of Items Observed:**

The Quality Assurance (QA) Inspector, Craig Hager was on site at berth 7 between the hours noted above. The QA Inspector was on site to randomly monitor and observe any fabrication performed by American Bridge/Fluor (ABF). The following observations were made:

The QA Inspector randomly observed and noted no work or fabrication was performed on the QA Inspectors shift. The QA Inspector performed job walks at various times through out the duration of the shift. The QA Inspector traveled to Yerba Buena Island to observe any work being performed. It was noted no work or fabrication was being performed at the various work stations identified above. The QA Inspector did not observe any ABF personnel on site.

This QA Inspector reviewed various submittals (drawings) for the project during the shift, in between performing the checks listed above.

Summary of Conversations:

No significant conversations this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mohammad Fatemi (916)813-3677, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By: Hager,Craig

Quality Assurance Inspector

Reviewed By: Levell,Bill

QA Reviewer